
SAMPLE INSPECTION

PROPERTY 1

INSPECTOR

PETER

INSPECTION DATE

30/01/2017

INSPECTION TIME



15:01



REPORT CREATED USING INSPECTR

TABLE OF CONTENTS

Bedroom 1 (Example)	3
Signature	4
Appendix	5

Bedroom 1 (Example)**Door** Clean, Undamaged**Walls** Clean, Undamaged**Ceiling** Clean, Undamaged**Floor** Dirty, Damaged*Notes: Red wine stain approximately 12 inches in diameter***Furniture & Furnishings** Clean, Undamaged**Photo(s) of Room***Appendix 1**Appendix 2**Appendix 3**Appendix 4**Appendix 5*

Signature**Inspector's Signature**

APPENDIX



Appendix: 1




Appendix: 2



Appendix: 3



Appendix: 4



Appendix: 5